

U.S. Department of Labor
Occupational Safety and Health Administration

Inspection Number: 1128326
Inspection Date(s): 02/24/2016 - 02/24/2016
Issuance Date: 03/23/2016



Citation and Notification of Penalty

Company Name: Front Street Millwork and Lumber
Inspection Site: 4622 Greyhawk Lane, Bismarck, ND 58504

Citation 1 Item 1 Type of Violation: **Serious**

29 CFR 1926.501(b)(13): Each employee(s) engaged in residential construction activities 6 feet (1.8 m) or more above lower levels were not protected by guardrail systems, safety net system, or personal fall arrest system:

Or in the alternative

29 CFR 1910.23(c)(1): Open-sided floor(s) or platform(s) 4 feet (1.22 m) or more above the adjacent floor or ground level were not guarded by standard railings (or the equivalent as specified in 29 CFR 1910.23(e)(3)(i) through (v)), on all open sides:

(a) On or about February 22, 2016 for an employee who fell approximately 20 feet while melting frost from the roof surface with a propane torch to prepare the working surface for shingle delivery at a single family construction project located at or near 4622 Greyhawk Lane in Bismarck, North Dakota.

Abatement certification and documentation are required for this item (see enclosed "Sample Abatement Certification Letter").

ABATEMENT DOCUMENTATION REQUIRED FOR THIS ITEM

Date By Which Violation Must be Abated:

03/29/2016

Proposed Penalty:

\$4900.00

A handwritten signature in black ink, appearing to read "Eric R. Brooks", written over a horizontal line.

Eric R. Brooks
Area Director

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.